

Church	Rectory	Convent
New choir risers	Roof leak repairs	Garage gutters repaired; trim replaced; siding repaired; painted
2 book cases; side entrances	Gutters cleaned	Sewage overflow problem from basement drains repaired
New collection basket cabinet	Pastor's suite renovated; new windows; painted; furnished	New chapel; painted; decorated; furnished
New collection basket liners	Guest bedroom renovated; repainted; furnished	Rain water down spout repaired; connected to sewer
Refurbished alter candlesticks	Parlor ceiling repairs; repainted;	Replaced radiator traps
Pew rebuild; located in rear	Kitchen cleaned out; reorganized; stovetop repairs	Fire extinguishers inspected/replaced; annual inspection instituted
Altar linens sorted, repaired, cleaned	Replaced copy machine	Kitchen plumbing repairs
Sacristy bathroom updated	Refurbished counter tops in kitchen	New exterior door locks
New floor in bathroom; rear of church	New boiler	Northside gutters cleaned out
New hand soap dispenses	Replaced radiator traps	Repair/replace the buckling convent back patio column (in process)
Sacristy windows repaired	First floor plumbing repairs	Replaced steps from the driveway to the convent sidewalk (in process)
Repainted display case in balcony	Basement area cleaned, organized, and repurposed	Installed hand-rail on front steps (in process)
New glass tops; tables and altars	Parlor room ceiling repaired; room painted; redecorated	
Repainted work shelf/table use for mass preparation	Glass block window foundation windows inspected; repaired; replaced	
Interior of church repaired; repainted	Repaired dish washer	
Stained glass windows washed	Fire extinguishers inspected/replaced; annual inspection instituted	
Four murals refurbished	Redecorated DRE office	
Increased lighting on murals	Redecorated Director of Music office	
Increased lighting on main alter	New phone system	
Rear church stairwells cleaned; painted	New exterior door locks	
Stations of cross refurbished; hung	Wooden fence repairs; repainted	
Church overhead lights retrofitted with LED lights	Antennae for TV reception in guest bedroom	
Church overhead light fixture repaired	New computer for DRE	
Phase 1 organ restoration	Refurbished computer for business manager	
Church slate roof repairs	Redecorated Office Manager office	
Glass block window foundation windows inspected; repaired; replaced	Second floor plumbing repairs	
New presiders chair	New cleaning service; expanded coverage	
Boiler repairs; regular twice yearly PM program	Created filing storage room; cleaned out/reorganized church sacramental	

	and business records	
Replaced broken radiator traps	Established Pastor office; redecorated and furnished	
Fire extinguishers inspected/replaced; annual inspection instituted	Repaired pastor office door	
Sewer basin cleaned out; recapped	Set up Business manager office	
Two rain water down spouts repaired; one connected to sewer	Repurposed; repaired dining room chairs	
New exterior door locks	Repaired pastor's upstairs room – floors, windows	
New altar candle globes	Boiler twice yearly maintenance program	
Refurbished decorations; original to church	Repaired 1 st floor air conditioner fan	
New cleaning service; expanded coverage	Installed new air conditioner access door panel	
Repaired front entrance steps to the Church	Repaired/replaced kitchen sink faucet fixture and counter tops	
Boiler feed water tank shut-off valve repaired (in process)	Repaired front entrance stairs	
Re-motored boiler chimney in church basement		
Repaired/replaced boiler chimney access door		
New CO and smoke alarm units installed in Church basement		